

Serviceable Tag



Head Office
WOW Air
Katrínartún 12
105 Reykjavík
Iceland

1. Serviceable Tag Number

Tag #: 3808



Runn. #: 8364

2. Part Name

HARNESS ASSY ROW 06RH

3. Part Number

1191-38

4. Serial number

096671

5. Aircraft mfg.

6. Component Status / Remarks

TSN: 0.000

CSN: 0

Cert. #: CAS4894

ATA:

R #: 8364

H. Note: COMOPONENT STATUS AS PER INCOMING CERTIFICATION AS STATED IN BLOCK 6

9. Vendor / Supplier

CABINAIR SERVICES

10. Site / Rack / Shelf

KEF/KEF 5/SEAT
PARTS/*

11. Purchase order

13607

12. Shelf life expiration

01-Jan-9999

Life limited parts will be accompanied by maintenance history including life

Receiving Inspection

Receiving inspection accomplished in accordance with CAME procedure, chapter 2-2.

13. Signature / Stamp

RMW



14. Approval reference number

IS.145.019

15. 3 letter code

RMW

16. Date (dd-mmm-yyyy)

26-Aug-2017

Installation Data

Forward to Maintenance Planning

17. Installed on A/C ref

18. Position

19. Site Code

20. Tech log page #

21. Date

22. Signature / Stamp

Removal Data

Duplicate removal data below

23. Part number

25. Component status

☐ Removed servicable

☐ Removed unservicable

24. Serial number

26. Reason for removal

☐ Timex

☐ Snag

☐ Tr.shoot

☐ Mod

☐ Incident

27. Failure / further description

17. Removed from A/C ref

18. Position

M-41 Rev. Original

Tear off

This line needs to be perforated

Component Identification Tag

Attach to removed component

Incoming Serviceable tag #: 3808

Runn. #: 8364



17. Removed from A/C ref

18. Position

19. Site Code

20. Tech log page

21. Date

22. Signature / Stamp

23. Part Number

24. Part Name

25. Serial number

26. Component status

☐ Removed servicable

☐ Removed unservicable

27. Reason for removal

☐ Timex

☐ Snag

☐ Tr.shoot

☐ Mod

☐ Incident

28. Work order #

29. Work card

30. Failure / further description

Gannet - ReportInventoryComponentTag

M-41 Rev. Original

WOW AIR - LETURPRENT