

1. Approving Competent Authority / Country CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number: WAV2105919	
4. Organization Name and Address: Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2105919 R383498	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Fire Extinguisher	898052	1.00	Y-364806	Repaired
12. Remarks: CMM: 26-21-39 Revision: 22 Next Overhaul/Hydrostatic Test Due: 2024. Last Overhaul/Hydrostatic Test: 2012. Last 6 Year Check: 06/2021. Checked Weight: 1.651 kg. Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.					
"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY183X"					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature:	13c. Certificate /Approval Ref No.:	14b. Authorised Signature: 		14c. Certificate /Approval Ref No.: UK. 145.00846	
13d. Name	13e. Date (dd/mm/yyyy):	14d. Name Luke Houghton		14e. Date (dd/mm/yyyy): 14/Jun/2021	
USER / INSTALLER RESPONSIBILITIES					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Competent Authority / Country EASA		2.		3. Form Tracking Number: WAV2105919		
4. Organization Name and Address: Avia Technique SK AeroSafety Group Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2105919 / R383498		
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:	
1	Fire Extinguisher	898052	1.00	Y-364806	Repaired	
12. Remarks: CMM: 26-21-39 Revision: 22 Next Overhaul/Hydrostatic Test Due: 2024. Last Overhaul/Hydrostatic Test: 2012. Last 6 Year Check: 06/2021. Checked Weight: 1.651 kg. Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12						
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14a. ☒ Part-145 A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.		
13d. Name		13e. Date (dd/mm/yyyy):		14b. Authorised Signature:  14c. Certificate /Approval Ref No.: EASA.UK.145.00846		
14d. Name Luke Houghton		14e. Date (dd/mm/yyyy): 14/Jun/2021				
USER / INSTALLER RESPONSIBILITIES						
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: WAV2105919

Date Printed: 04/06/2021

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R383498

Date Received: 25/05/2021

Part Number: 898052

Description: Fire Extinguisher

Serial Number: Y-364806

Customer Remarks:

Repair

Seal Broken

Results from inspection:

Faults:

Neck Seal is damaged.

Pin Pull missing.

Last HST 2012.

Corrective actions:

Repair and Test with reference to correct CMM

Replace Neck Seal and Pull Pin.

Inspection report generated by: Jonathan Kraty