1. Approving Competent Authority/Country	2. AUTORISED RELEASE CERTIFICATE	3. Form Tracking Number
Luftfahrt Bundesamt Germany	**EASA FORM 1**	S19/1604 S

4. Organisation Name and Adress	5. Work Order/Contract/Invoice
Safran Cabin Germany GmbH Dr.-Siegfried-Str. 0 D-35745 Herborn, Germany	10019121

6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status/Work
000001	OVEN STEAM	8053-03-0000-00	1.000	08-04-0754	REPAIRED

12. Remarks Organisation name change from Sell GmbH to Safran Cabin Germany GmbH by trade registration

Customer: A.J. WALTER AVIATION LTD.
Repaired in accordance with Job Card 300010917 and CMM 25-36-81 Issue 02.

13a. Certifies that the items identified above were manufactured in conformity to:	14a. ☒ Part 145.A.50 Release to Service ☐ Other regulation specified in block 12
☐ approved design data and in a condition for safe operation ☐ non-approved design data specified in block 12	Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service

13b. Authorised Signature	13c. Approval / Authorisation Number	14b. Authorised Signature	14c. Certificate / Approval Ref. No
	DE.21G.0090	Certifying Staff · C/S 037 · Safran Cabin	DE.145.0330
13d. Name	**13e. Date (dd mm yyyy)**	**14d. Name**	**14e. Date (dd mm yyyy)**
		J. Groos	19 MAR 2019

USER / INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user / installer performs work in accordance with regulations of an airworthiness authority other than the airworthiness authority specified in block 1, it is essential that the user / installer ensures that his / her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user / installer before the aircraft may be flown.

ORIGINAL

ZODIAC GALLEY INSERTS

ZODIAC GALLEYS & EQUIPMENT

ZODIAC AEROSPACE

U. Band

Job Card Maintenance
EASA Part 145 - Approval DE. 145.0330

Notification 300010917

Creating date: 09.01.19

Customer: A.J. WALTER AVIATION LTD.

Order No.: 50010721

Reference No.: W44576 | 2019-01-08

Equipment: OVEN 8053-03-0000-00

Removal Reason: no heating

Serial no: 08-04-0754

Location of Work: Herborn-Burg

Contact person: Andreas Peter

Email: Andreas.Peter@zodiacaerospace.com

Phone: 0 2772 707 | 183

Removal reason confirmed? (X) no ( ) yes

Reusable Package? (X) nein ( ) yes

(•) Reparatur Part 145 ( ) Modifikation Part 145 ( ) Nachprüfung Part 145 ( ) Überholung Part 145 ( ) NTW Part 21

Manuals

Page 1 to 2

Item 1 to 8

RM: N/A

CMM: CMM 25-36-81 Version: 02

IPC / IPL: N/A N/A

AD/LTA (X) no ( ) yes N/A

Tested by: Q124

Date: 09 JAN 2019 Name: Benjamin Strauß

Signature

Qualified Employee 171573

Certifying Staff J. Groos

Date beginning 14. MRZ. 2019

Date finishing 18. MRZ. 2019

Inspected and Released

Date 19 MAR 2019 Name: J. Groos

Signature

Certifying Staff C/S 037 Safran Cabin

Release by Customer

Date Name: Signature

QVA-016.frm-1 A02

ZODIAC GALLEY INSERTS

ZODIAC GALLEYS & EQUIPMENT

ZODIAC AEROSPACE


Job Card Maintenance EASA Part 145 - Approval DE. 145.0330	Notification	300010917	Creating date:	09.01.19

Description of repair / Modification / Corrective Action to be done					Works performed	Inspection
Item No	Discrepancies or Modification-Requirements			Action to be taken	Signature / Date	Release / Stamp and Date
1	Outer Casing	Damaged		new –	171573 18. MRZ. 2019	19 MAR 2019 Q08
2	Inner Casing	Dirty		clean –	171573 18. MRZ. 2019	19 MAR 2019 Q08
3	Wiring	Wrong	GD09	rework –	171573 18. MRZ. 2019	19 MAR 2019 Q08
4	Door	Repainted by customer		new –	171573 18. MRZ. 2019	19 MAR 2019 Q08
5	Baffle Plate	Discoloured		new –	171573 18. MRZ. 2019	19 MAR 2019 Q08
6	Water System	Dirty		clean –	171573 18. MRZ. 2019	19 MAR 2019 Q08
7	Door seal	Worn		new –	171573 18. MRZ. 2019	19 MAR 2019 Q08
9	coupling-connector	Stiff		new –	171573 18. MRZ. 2019	19 MAR 2019 Q08


Externe Vermerke

Ofen Typ	Serien Nummer	Befundbericht Nummer
8053-03-0000-00	08-04-0754	300010917

Eingangskontrolle



Schreiber 1 Innenraumtemperatur




Schreiber 1 Dampfheizungstemperatur


Datum: 09 JAN 2013 Prüfer: Beniamin Strauß Stempel: Q 124

Ofen Typ	Serien Nummer	Befundbericht Nummer
8053-03-0000-00	08-04-0754	300010917

Endkontrolle



Schreiber 5 Innenraumtemperatur



Schreiber 5 Dampfheizungstemperatur

Datum: 19 MAR 2019 Prüfer: J. Groos Stempel: Q08