


1. Approving Civil Aviation Authority/Country Transport Canada		2.		3. Form Tracking Number. WO1736	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: 210712	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Cabin Handset	89-01-07162	1.00	174884	REPAIRED
12. REMARKS REPLACED SPEAKER, MICROPHONE, FRONT AND BACK HOUSING. REPAIRED IN ACCORDANCE WITH CMM 23-73-01 REV#14, DATED JAN 12/2012.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12					
13b. Signature:		13c. Approved Organization Number		14b. Signature	
					
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed)	
				Serge Morin	
				14c. Approval Organization Number 33-12	
				14e. Date (dd/mm/yyyy) 27/Aug/2013	
This certificate does not constitute authority to install the part.					
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW Technique Inc.

7055 ALEXANDER-FLEMING
SAINT-LAURENT, QC H4S-2B7
CANADA
Ph: (514)339-5100, Fax: (514)339-5246



Tear Down/Inspection Report

Work Order #: WO1736

Date Printed: 27/08/2013

Time: 18:29:48

Page: 1

To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Customer RO: 210712

Phone #: +44 1403 798000

Fax #:

Email: progressing@ajw-aviation.com

Code: AJW01

PN: 89-01-07162

Serial #: 174884

Qty: 1

Descr: Cabin Handset

Mfg: HOLMBERG GMBH

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

Engine #:

Tail #:

P/N Out: 89-01-07162

Serial # out: 174884

Symptoms:

CODE: FUNCTIONAL DEFFECT

DETAILS: NO SOUND AFTER CALL
A/C REG: PAOAS

Faults:

CODE: ELECTRICAL FAILURE

DETAILS: BROKEN WIRE ON SPEAKER, BROKEN CASE.
FAILED MICROPHONE SENSIBILITY TEST.

Need to replace:

-Microphone p/n 80-22-96844

-Speaker p/n 80-01-96825

-Case p/n 33-03-00010 and 27-14-90018

Corrective Actions:

CODE: REPAIRED

DETAILS: REPLACED SPEAKER, MICROPHONE, FRONT AND BACK HOUSING.
REPAIRED IN ACCORDANCE WITH CMM 23-73-01 REV#14, DATED JAN 12/2012.

PN	Description	Reason	Qty Needed	CD	Disposition
27-14-90018	BACK PART HSNG H	broken	1	NE	Consumable
33-03-00010	MAIN HOUSING HOU	broken	1	NE	Consumable
80-01-96825	RECEIVER CAPSULE	broken	1	NE	Consumable
80-22-96844	MICROPHONE UNIT I	failed test	1	NE	Consumable