


1. Approving Competent Authority / Country CAA UK		AUTHORISED RELEASE CERTIFICATE CAA FORM 1				61900214 3. Form Tracking Number 21578055 00000001																					
4. Organisation Name and Address  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		5. Work Order / Contract / Invoice 61900214																									
6. Item 01	7. Description VALVE SCAVENGE BRG NO.4	8. Part No. 32F0003	9. Qty. 1	10. Serial No. TE023179	11. Status / Work OVERHAULED																						
12. Remarks ATA 7923 TP O MK-No. 10 Pack Code 00 Resp. Workshop 33332030 Workshop Station HAM063 A.J. Walter (Aviation) Ltd. R399785 <table border="1"> <thead> <tr> <th></th> <th>Opr. Hours</th> <th>Cycle</th> <th>Opr. Day</th> </tr> </thead> <tbody> <tr> <td>TT</td> <td>UNKNOWN</td> <td>UNKNOWN</td> <td>UNKNOWN</td> </tr> <tr> <td>TSO</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>TSC</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>TSF</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table> TASK PERFORMED IN ACCORDANCE WITH CMM 79-23-52 REV. 1 / CMDS 79-23-52 ISSUE 012									Opr. Hours	Cycle	Opr. Day	TT	UNKNOWN	UNKNOWN	UNKNOWN	TSO	0	0	0	TSC	0	0	0	TSF	0	0	0
	Opr. Hours	Cycle	Opr. Day																								
TT	UNKNOWN	UNKNOWN	UNKNOWN																								
TSO	0	0	0																								
TSC	0	0	0																								
TSF	0	0	0																								
☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents. 14a. ☒ Part - 145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service. ☐ Other Regulation specified in block 12																											
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		13b. Authorised Signature 		13c. Approval / Authorisation Number 532925		14c. Certificate / Approval Ref. Number UK.145.01408																					
13d. Name Miriam Schulze		13e. Date (dd mmm yyyy) 24 Sep 2022		14d. Name Miriam Schulze		14e. Date (dd mmm yyyy) 24 Sep 2022																					

USER / INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

RFID-Smartlabel

61900214



Ident-Tag Barcode

Ident-Tag**Lufthansa Technik**

Form Tracking Number

21578055 00000001

Work Order / Contract / Invoice

Description

VALVE SCAVENGE BRG.NO.4

Part. No.

32F0003

Eligibility

Quantity

1

Status / Work

OVERHAULED

Serial-/Batch No.

TE023179

Remarks

TP O MK-No. 10

Resp. Workshop 33332030 Workshop Station HAM063

FSCM B1316 ATA

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

RemovedPNR¹SNR¹Position/FIN No.¹Station¹A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹☐ 22 UnscheduledComplaint No.¹ or WO-Reference¹☐ 11 ScheduledFailure Description¹ (Please write in capital letters only)CCI-ID²

Special Investigation Tag exists

☐ YesStamp or ID Number + Signature^{1/2}Date¹**Please send back to:**(unless other return location is agreed)

LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLSEBUETTEL
Deutschland

(LTLS-Information: Use this box for ZID)

¹ Mandatory entries without using CCI-Mask² Mandatory entries using CCI-Mask

LHT Form 31794 E-20 (FRA T/FS-QP)

Workshop Report



Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Lufthansa Technik

Customer Order No. R399785

61900214

Certificate Ref. No.

21578055 00000001

Work Order/Contract/Invoice

61900214

Part No. as received

32F0003

Serial No. as received

TE023179

Part No. as dispatched

32F0003

Serial No. as dispatched

TE023179

Reason for removal

RFR: NOT WORKING PROPERLY

Findings

ALL SEALS, POPPET AND ALL PACKINGS WORN.
INTERNAL PARTS HEAVY CONTAMINATED WITH OIL
INTERNAL LEAKAGE OUT OF GMM GIVEN LIMIT.
SCRATCHES IN PISTON-BORE OF VALVE-BODY FOUND(SURFACE CAN BE POLISHED)

Action

VALVE CLEANED, OVERHAULED AND TESTED.
PISTON-BORE POLISHED AND ANODIZED

See Unit Mod-Label if equipped

Modification Status according to Mod-Label

Name

532925, Miriam Schulze

Date (dd mm yy)

24 Sep 2022

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.