




1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 20180004251769Y15 331225499	
4. Organization Name and Address: Honeywell International Inc 4150 Lind Avenue SW RENTON WA 98057		Repair Station RN3R821L		5. Work Order/Contract/Invoice Number: 8148480 331207483 Page 1 of 1		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:	
001	COMPUTER,DIGITAL- CPM-GRAPHICS GEN	4075400-902	1	99031501	OVERHAULED	
12. Remarks: THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 31-41-34 Rev 12, JUN/26/2006 SB 4075400-31-0014 Rev 01, MAY/09/2003 UNIT ALSO MODIFIED MODS: A, C, E						
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4534						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14c. Approval/Certificate No.: RN3R821L		
13b. Authorized Signature:		14b. Authorized Signature: 		14e. Date(dd/mm/yyyy): 31/JAN/2018		
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): Jeanna Liess				
13e. Date(dd/mm/yyyy):						
User / Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 11, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 11. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. FAA FORM 8130 - 3 (02-14)						



参阅产品目录详细查找适用性

Cross - check eligibility for more details with parts catalogue

AAC - 038(12/94)

SERVICE REPORT

HAT - Phoenix

SR NUMBER: 5011943449		331225499	FAA: RN3R821L	EASA: 145.4534
PO: 8148480	CUSTOMER PART NUMBER:		CONTRACT NUMBER:	
DATE REJECTED: 25 JAN 2018	DATE RECEIVED: 25 JAN 2018		DATE COMPLETED: 31 JAN 2018	
A/C TYPE: UNK	A/C TAIL NUMBER:		A/C SERIAL NUMBER:	
PACKING STATUS: No	SEALS INTACT: Intact		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: QAR # CN36789 FAILS FT: HRC2100000 19 0102 ASSERTED DURING DECK 2 ENGINE RUN.				
PART NUMBER	AS RECEIVED: 4075400-902		AS RELEASED: 4075400-902	
DESCRIPTION:	COMPUTER,DIGITAL- CPM-GRAPHICS GEN		COMPUTER,DIGITAL- CPM-GRAPHICS GEN	
SERIAL NUMBER	99031501		99031501	
UID(MFR/SPL PNO SER/UCN)	58960 1726448		58960 1726448	
HW MOD STATUS:	A, E		A, C, E	
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed			ESTIMATE SUPPLIED: No	
PRIMARY SHOP FINDING: No Fault Found			WARRANTY:	
TYPE OF SERVICE: OVERHAULED/Modified			TECHNICIAN: Jeffrey Caoagdan	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 31-41-34/Rev 12/Rev Date 26 JUN 2006; Service Bulletins: 4075400-31-0014/Rev 01/Rev Date 09 MAY 2003; Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

HAT - Phoenix

800-601-3099 (T) 602-822-9194 (F)

SR NUMBER: 5011943449		FAA: RN3R821L	EASA: 145.4534
PO: 8148480	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
CMM/Eng Documentation:
Service Bulletins:
Customer Manuals/Documentation:

Work performed / Comments to Customer

UNIT HAS BEEN OVERHAULED BY ASSESSTMENT. DISASSEMBLED THE UNIT TO CCA LEVEL. INSPECTED AND CLEANED INTERNAL COMPONENTS AS NECESSARY. NO HIDDEN DAMAGE FOUND. UNIT PASSED ALL TESTING IN SHOP. PERFORMED TEMPERATURE-CYCLE HOT/COLD POWER UP BITE TESTING. NO REPAIRS REQUIRED AT THIS TIME. INSTALLED LATEST SERVICE BULLETIN TO IMPROVE HARDWARE RELIABILITY.

INSTALLED MOD 'C' PER SB 4075400-31-0014 REV 001 BY INSPECTION.

PASSED FUNCTIONAL TEST. TEST EQUIPMENT CALIBRATION DATES CHECKED AND UNIT FINAL TESTED BY H268581 ON 29JAN2018. THIS COMPONENT IS AIRWORTHY WITH RESPECT TO THE WORK PERFORMED. COMPLIES WITH AW/PS PRODUCTION CRITICAL REQUIREMENTS.

NO OPERATIONAL SOFTWARE LOADED TO UNIT.

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
-------------	---------	------------------	------------------	----------------	----------------	-----	--------------------	----

RTS TECHNICIAN

DATE

JAN 31 2018