


1. Approving Civil Aviation Authority/ Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: 182765	
4. Organization Name and Address: AVIATION INSTRUMENTS REPAIR SPECIALISTS, INC. (DBA A.I.R.S.) VTBR433V A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A. Phone: 305-887-5600, Fax: 305-820-0931				5. Work Order/Contract/ Invoice Number: R417913	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ICE DETECTOR	0871DP4	1	2612	REPAIRED
12. Remarks: REPAIRED in accordance with CMM 30-81-31, Revision 3, Date Mar 08, 2021 Full details of work carried out per work order no. 182765 Modification Level: N/A Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part - 145 and in respect to that work ICE DETECTOR is considered ready for release to service under EASA Part - 145 approval no. EASA.145.5033 FAA Ad's: NONE EASA Ad's: NONE					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.			14.a ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: Not Applicable		13c. Approval/Authorization No.: Not Applicable		14b. Authorized Signature: 	
13d. Name (Typed or Printed): Not Applicable		13e. Date (dd/mm/yyyy) Not Applicable		14c. Approval/Certificate No.: VTBR433V	
				14d. Name (Typed or Printed): Marshall Garber	
				14e. Date (dd/mm/yyyy): 10/Oct/2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

AVIATION INSTRUMENTS REPAIR SPECIALISTS, INC. (DBA A.I.R.S.)

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: 305-887-5600

Fax: 305-820-0931

C.R.S. No.: VTBR433V

Work Order: 182765

Date: October/10/2023

Sold to:

A J WALTER AVIATION Ltd
The Headquarters, Maydwell Ave.
Slinfold, West Sussex, RH13 0AS
United Kingdom

Ship to:

A J WALTER AVIATION Ltd.
THE HEADQUARTERS, MAYDWELL AVENUE
West Sussex, Slinfold, 0 RH13 0AS
United Kingdom

Part Number: 0871DP4

Serial: 2612

Manufacturer: COLLINS AEROSPACE

Description: ICE DETECTOR

Model: VARIOUS

Purchase Order: R417913

Service Performed: REPAIRED

Data used:

Manual Number: 862

Revision: 3

Date: 03/08/2021

Teardown/Inspection Data

1. Removal: NONE

Inst.: REPAIRED

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Loose or Missing Parts: No Loose or Missing Parts

Mod. Level: N/A

Corrosion: No Corrosion Noted

Physical Damage: Contaminated

3. Teardown

Disassembly: Normal

Painting: Normal Painting

Cleaning: Normal Cleaning

Assembly: Normal Assembly

4. Test

Operation: Operation I/A/W Mfg. Specs

Was Complaint Verified: No

Mods. Completed: None

5. Final

Warranty Accepted: N/A

Final Test and Inspection: Final Inspection Normal

T.S.O.: N/A

A.T.A.: 30-81-31

A.D. S.B.: NO A.D. / S.B REQUIRED

6. Work Done

UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, ASSEMBLED. SOLDERED FL1, REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 30-81-31. WORK PERFORMED BY Tito Rodriguez.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect of the work performed is approved to service. Pertinent details of the work performed are on File at this Agency under Work Order: 182765

Inspector: Marshall Garber

Certificate No. 2506369

Technician: Tito Rodriguez

Signature: _____

Date: October/10/2023

Form: CRS-3



Aviation Instruments Repair Specialists, Inc. (dba A.I.R.S.)
/ EASA.145.5033
14316 COMMERCE WAY
MIAMI LAKES, FL 33016
Phone: 305-887-5600
Fax: 305-820-0931
E-Mail: info@airs-inc.com

SHIPPER DATE: 10/10/2023

Shipping Ticket

SHIPPER #:
130280

Bill To:

A J WALTER AVIATION LTD
THE HEADQUARTERS, MAYDWELL AVE.
SLINFOLD, WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Shipped To:

A J WALTER AVIATION LTD.
THE HEADQUARTERS, MAYDWELL AVENUE
WEST SUSSEX, SLINFOLD, 0 RH13 0AS
UNITED KINGDOM

Order Date: 10/06/2023

Customer RO #: R417913

Work Order #: 182765

Customer #: 1866

Terms: 45 days

F.O.B: Miami Lakes

Ship Via: FedEx

Shipping Notes: 124277507

<u>P/N</u>	<u>Description</u>	<u>Qty</u>	<u>S/N</u>	<u>Condition</u>
0871DP4	ICE DETECTOR	1	2612	REPAIRED

From:

Aviation Instruments Repair Specialists,
Inc. (dba A.I.R.S.)
14316 COMMERCE WAY
MIAMI LAKES, FL 33016

Print Name: _____

Signature: _____

Date: _____

Packing CheckList:

Yes No NA

Part Number [] [] []

Serial Number [] [] []

Form 8130-3 [] [] []

Cert. Trace [] [] []

Forms Audit [] [] []

Bubble Wrap [] [] []

To: POIRO#: R417913
A J WALTER AVIATION LTD.
THE HEADQUARTERS, MAYDWELL
AVENUE
WEST SUSSEX, SLINFOLD, 0 RH13
0AS
UNITED KINGDOM
Phone: 011441403711777